

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER



7. Unit Agreement Name

8. Farm or Lease Name
John Shults

9. Well No.
6

10. Field and Pool, or Wildcat
Gladiola Devonian



12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3875' GR

2. Name of Operator ARCO Oil and Gas Company
Division of Atlantic Richfield Company

3. Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER I 660 FEET FROM THE East LINE AND 1980 FEET FROM
THE South LINE, SECTION 13 TOWNSHIP 12S RANGE 37E NMPM.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	Devonian zone only	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to cancel plug and abandoning of well as approved on February 3, 1982 and abandon Devonian zone only and recomplete to Mississippian in the following manner:

- Rig up, kill well, install BOP & POH w/compl assy.
- Set cmt retr @ 11,800' inside 5½" csg. Squeeze cmt Devonian perforations 11,911-11,927'. Press test csg to 1500#.

Recompletion procedure to test Mississippian zone reported separately on Form C-101.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth S. Bush TITLE Drlg. Engr. DATE 10/14/83

APPROVED BY JERRY SEXTON DISTRICT 1 SUPERVISOR TITLE _____ DATE _____

OCT 19 1983