

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name Markham Unit
2. Name of Operator Shell Oil Company	8. Farm or Lease Name Markham
3. Address of Operator P. O. Box 1858, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE south LINE AND 1980 FEET FROM THE west LINE, SECTION 23 TOWNSHIP 12-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Gladiola
15. Elevation (Show whether DF, RT, GR, etc.) 3898 df	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and pump
2. Unseat Model R packer. Pull tubing and packer.
3. Run tubing open ended and circulate hole with mud.
4. Spot the following plugs:
25 sx over perforations 9744' - 9772'.
10 sx at surface.
5. Erect surface marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By R. J. Doubek TITLE Division Mechanical Engr. DATE Jan. 4, 1965

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: