

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

E-9697

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)OIL
WELL ☒GAS
WELL ☐OTHER ☐

1. Name of Operator

Dwight A. Tipton

2. Address of Operator

c/o Oil Reports & Gas Services, Inc., P. O. Box 755, Hobbs, NM 88241

3. Location of Well

UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROMTHE East LINE, SECTION 22 TOWNSHIP 14S RANGE 34E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

High Plains

9. Well No.

1

10. Field and Pool, or Wildcat

High Plains Permo Penn

15. Elevation (Show whether DF, RT, GR, etc.)

4103.9

12. County

Lea

6.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐CHANGE PLANS ☐REMEDIAL WORK ☒COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOB ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work began 5/24/85. Set retrievable bridge plug at 10,300, Perforate 9644-9650 with 2 shots per foot. Treat with 1,000 gallons 15% NEFE Acid. Swab load. 5/30/85 pump 77 bbls oil, 14 bbls water, 24 hours.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE AgentDATE 5/31/85ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN - 4 1985