

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 2359

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Harris AAU State
Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 14S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Wildcat <i>See attached</i>
15. Elevation (Show whether DF, RT, GR, etc.) 4187.1' GR	12. County Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Perforate, Treat <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

TD 10185'. WIH and perforated 9937-9946' w/10 .42" holes as follows: 9937, 38, 39, 40, 41, 42, 43, 44, 45 and 46'. Acidized perfs 9937-46' w/2000 gals 15% NEFE acid and ball sealers. Swabbed well. WIH and perforated 9844-9919' w/19 .42" holes as follows: 9844, 45, 46, 47, 48, 49, 60, 61, 62, 63, 64, 9905, 06, 10, 11, 12, 17, 18 and 19'. Acidized perfs 9844-64' w/2000 gals 15% NEFE acid and ball sealers. Acidized perfs 9905-19' w/1000 gals 15% NEFE acid and ball sealers.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor DATE 1-8-85

ORIGINAL SIGNED BY JERRY SEXTON

JAN 16 1985

APPROVED BY DISTRICT SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: