

Submit 3 Copies to Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resource

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-29312
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-251
7. Lease Name or Unit Agreement Name: Saunders 28 B State
8. Well No. 1
9. Pool name or Wildcat Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other P & A <input type="checkbox"/>	
2. Name of Operator Caprock Exploration, Inc.	
3. Address of Operator P. O. Box 7288 - Odessa, TX 79760	
4. Well Location Unit Letter <u>L</u> : <u>1980</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>28</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> Approved as to plugging of the Well Bore. Liability under bond is retained until <input type="checkbox"/> OTHER: surface restoration is completed. <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-23-2002 - Moved in and rigged up pulling unit and plugging equipment. Nippled down wellhead and nipped up BOP. Released tubing. POOH with 2-7/8" tubing. Shut well in for night.

3-24-25-2002 - Shut down for weekend.

3-26-2002 - POOH with tubing. Changed out brakes and blocks on rig. Rigged up wireline. TIH with CIBP and set CIBP at 9720'. Capped CIBP with 20' of cement. Rigged down wireline. Shut well in for night.

3-27-2002 - TIH with 2-3/8" tubign and tagged plug at 9700'. Circulated hole with plugging mud. POOH with tubing. Nippled down BOP. Shut well in for night.

3-28-2002 - Nippled down wellhead. Tried to pull slips. Could not. BEH and shot 5-1/2" casing at 6000'. Tried to pull slips. Wrapped wellhead with pecmer cord. Could not pull slips. Cut 5-1/2" casing at 5458'. Picked up on casing at right angle - box broke. Shut well in for night.

3-30-2002 - Put right angle BOP on and pulled slips. Worked pipe for 3 hours. Stuck at 2000'. Pumped 100 barrels fresh water down backside of 5-1/2" casing. Free up down to

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Agent for BCM & Associates DATE April 8, 2002

Type or print name Rusty Klein Telephone No. 505-746-6565

(This space for State use)

APPROVED BY Harry W. Wink Approved as to plugging of the Well Bore.
Liability under bond is retained until DATE
Conditions of approval, if any: GWW surface restoration is completed.

JAN 16 2003