

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>Union Oil Company of California</b>		8. Farm or Lease Name <b>Bracken</b>
3. Address of Operator <b>P. O. Box 671, Midland, Texas 79701</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1,980</b> FEET FROM THE <b>North</b> LINE AND <b>1,980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>2</b> TOWNSHIP <b>7-S</b> RANGE <b>32-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4,450' GR</b>		12. County <b>Roosevelt</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to 4,400' and perforated 4-1/2" O.D. casing 4,279' to 4,285', acidized and swabbed, well failed to produce. Received verbal permission from Mr. Ingbrecht 11-15-67 to plug and abandon. Plugged well as follows:

Plug #1 - 25 sx. cement 4,290' to 4,040'. Cut 4-1/2" casing at 1,445' and recovered 1,436'

Plug #2 - 50 sx. cement 1,500' to 1,330'.

Plug #3 - 50 sx. cement 422' to 262'.

Plug #4 - 10 sx. cement 30' to 0'.

Cut off 8-5/8" casing head and welded steel plate on 8-5/8" casing with needle valve on vent. Installed dry hole marker. Plugging complete 11-17-67.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R.G. Ladd, Jr.</u>	TITLE <u>District Drilling Supt.</u>	DATE <u>11-20-67</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>          </u>
CONDITIONS OF APPROVAL, IF ANY:		