

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**E-604**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -----
2. Name of Operator <b>Morris R. Antweil</b>	8. Farm or Lease Name <b>New Mexico "AH" State</b>
3. Address of Operator <b>Box 2010, Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM <b>West</b> LINE, SECTION <b>36</b> TOWNSHIP <b>15</b> RANGE <b>34</b> NMPM.	10. Field and Pool, or Wildcat <b>Townsend Wolfcamp</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4046' DF</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Propose to plug and abandon as follows:**  
**spot 25 sx cement plug across perfs 9640'- 9658'**  
**cut and pull an estimated 3100' 5-1/2" casing.**  
**spot 25 sx. cement plug across 5-1/2" casing stub @ 3100'.**  
**cut and pull an estimated 890' 9-5/8" casing.**  
**spot 25 sx. cement plug across 9-5/8" casing stub @ 890'.**  
**spot 25 sx. cement plug across 13-3/8" casing shoe @ 423'**  
**10 sx. cement surface plug w/marker.**  
**Hole will be loaded with mud laden fluid.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R M Williams TITLE Agent DATE 1-17-69

APPROVED BY John W. Ruygan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: