

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-2929

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Exxon Corporation 3. Address of Operator Box 1600, Midland, TX 79702 4. Location of Well UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM West LINE, SECTION 36 TOWNSHIP 15 RANGE 35 NMPM. 15. Elevation (Show whether DF, RT, GR, etc.)	7. Unit Agreement Name 8. Farm or Lease Name New Mexico "AP" State 9. Well No. 1 10. Field and Pool, or Wildcat Dean Permo, Penn. 12. County
--	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled production equipment.
2. Set cibp at 10,400' w/4 sacks cement cap.
3. Perf 5½" casing 10,175 - 9,902 w/168 shots.
4. Acidize perfs 10,175 - 9,902 w/12,000 gallons 15% NE HCL acid.
5. Placed well on pump.
6. Tested well 15 days, recovered 238 Bbls. load water plus 994 Bbls. formation water.
7. Well under study. FRW 10-29-81

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Sr. Administrator DATE 11-11-81

APPROVED BY [Signature] TITLE DATE NOV 18 1981
CONDITIONS OF APPROVAL, IF ANY:



LTR



Job separation sheet

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-2929

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Farm or Lease Name New Mexico "AP" State
3. Address of Operator Box 1600, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>15</u> RANGE <u>36</u> NMPM.	10. Field and Pool, or Wildcat Dean Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3854 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1. Pull production equipment.
2. Set CIBP @ 10,400± and cap w/43k5 cmt.
3. Perf 9902-10175 w/168 shots.
4. Acidize w/12,000 gal 15% NEHCL Acid
5. Run production equipment - place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. P. L... TITLE Sr. Administrator DATE 8-11-81

APPROVED BY Jerry Sexton TITLE DATE AUG 17 1981

CONDITIONS OF APPROVAL, IF ANY: