

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Charles B. Read	5. State Oil & Gas Lease No. -
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201	7. Unit Agreement Name -
4. Location of Well UNIT LETTER <u>J</u> , 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>15S</u> RANGE <u>36E</u> NMPM.	8. Farm or Lease Name Alexander
	9. Well No. 1
	10. Field and Pool, or Wildcat UNDESIGNATED
15. Elevation (Show whether DF, RT, GR, etc.) 3902.5 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. To set a 25 sx cement plug at 10,500'
Cut and remove 5½" csg. at 9700'
To set a 25 sx cement plug at 9750 - 9650'
To set a 25 sx cement plug at 8300' to 8200'
To set a 25 sx cement plug at 6400' to 6300'
To set a 25 sx cement plug at 4900' to 4800'
Cut and remove 8 5/8" csg at 1200'
To set a 25 sx cement plug at 1250' to 1150'
To set a 25 sx cement plug at 450' to 350'
To set a 25 sx cement plug at 25' to 0'

2. Erect regulation marker

3. To clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE July 15, 1968
PROVED BY [Signature] TITLE SUPERVISOR DISTRICT 1 DATE 7/15/68
CONDITIONS OF APPROVAL, IF ANY: