

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

PAGE - 2

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator J. C. BARNES OIL CO.	8. Farm or Lease Name DENTON
3. Address of Operator P.O. BOX-505, MIDLAND, TEXAS 79701	9. Well No. 1
4. Location of Well UNIT LETTER 0, 990' FEET FROM THE SOUTH LINE AND 1980' FEET FROM THE EAST LINE, SECTION 11 TOWNSHIP T-15-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat DENTON (DEV.)
15. Elevation (Show whether DF, RT, GR, etc.) 3788' GR.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER STUCK DRLG. PIPE. <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5-10-77 STUCK (SPILL). CHAINED OUT OF HOLE. LAID DOWN JARS & BOTTOM HOLE COLLAR. TIH W/BIT. WASHED TO TOP OF FISH @ 11,273'. DISPLACED SULPHUR WATER TO MIX MUD. CIRC. & CONDITIONED MUD. START OUT OF HOLE TO PICK UP WASH PIPE.
- 5-11-77 STILL STUCK/FISH IN HOLE. COND. MUD & TRIPPED OUT. PICKED UP WASH PIPE & FISHING TOOLS. CHGD. OUT DRLG. LINE. TIH W/WASH PIPE. WASHED ON TOP OF FISH @ 11,271'. WASHED TO TOP OF STABILIZER & LOST CIRC. WORKED WASH PIPE, JARRED PIPE LOOSE @ 11,298'. TRIPPED OUT. GOING BIH W/THREAD END OF DRILL COLLAR & SCREW INTO FISH.
- 5-12-77 STILL STUCK. TRIPPED OUT WASH PIPE. COND. MUD. PICKED UP SCREW-IN SUB & FISHING TOOLS & WIH. SCREWED INTO FISH BUT UNABLE TO GET GOOD ENOUGH HOLD TO BRING IT OUT. TRIPPED OUT OF HOLE. TIH W/OVERSHOT. WORKED OVER FISH. CHAINING OUT OF HOLE. NO RECOVERY.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. Vandenberg TITLE PRODUCTION ACCNT. DATE 7-6-77

APPROVED BY John W. Runyan TITLE Geologist JUL 12 1977  
CONDITIONS OF APPROVAL, IF ANY:

CONFIDENTIAL

APR 13 1977  
OIL CONSERVATION COM. COMM.  
HOBBS, N. M.