

**DUPLICATE**

NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

**MISCELLANEOUS NOTICES**

**RECEIVED**  
 JUN 9 1948  
**RECEIVED**  
 HOBSB OFFICE

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL			

Hobbs, New Mexico

June 8, 1948

Place

Date

OIL CONSERVATION COMMISSION,  
 Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the

The Ohio Oil Company State Land Sec. 32 Well No. 7 in SE/4, SE/4  
Company or Operator Lease  
 of Sec. 32, T. 18-S, R. 38-E, N. M. P. M., Bowers Field.  
Lea County.

**FULL DETAILS OF PROPOSED PLAN OF WORK**

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Total depth 301' Red Beds. Ran 9 joints 8-5/8" casing set @ 301' cemented w/125 sacks regular cement. Plug pumped down @ 10:10 P.M. 6-7-48. Will test and drill plug at approximately 10:10 P.M. 6-8-48.

Approved \_\_\_\_\_ IN \_\_\_\_\_ 19\_\_\_\_  
 except as follows:

The Ohio Oil Company  
Company or Operator  
 By P. B. Stewart  
 Position Superintendent  
 Send communications regarding well to  
 Name The Ohio Oil Company  
 Address Box 1607  
Hobbs, New Mexico

OIL CONSERVATION COMMISSION,  
 By Roy Yunkerough  
 Title \_\_\_\_\_

Faint, illegible text covering the majority of the page, likely bleed-through from the reverse side of the document.

NOV 10 1950

Faint, illegible text at the bottom of the page, possibly a footer or additional bleed-through.