

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other instructions  
verse side)

TE  
re

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

NM-4609

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
Mewbourne Oil Company

3. ADDRESS OF OPERATOR  
P. O. Box 7698, Tyler, Texas 75711

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1980' FNL & ~~660'~~ FEL  
330

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Federal "E"

9. WELL NO.  
12

10. FIELD AND POOL OR WILDCAT  
Oquerecho Plains - Upper  
Bone Springs

11. SEC., T., S., M., OR BLE. AND SURVEY OR AREA  
27-18S-32E

14. PERMIT NO.  
API #30-025-29629

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3751.1'

12. COUNTY OR PARISH  
Lea

13. STATE  
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF   
FRACTURE TREAT   
SHOOT OR ACIDIZE   
REPAIR WELL   
(Other)

PULL OR ALTER CASING   
MULTIPLE COMPLETE   
ABANDON\*   
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF   
FRACTURE TREATMENT   
SHOOTING OR ACIDIZING   
(Other) Set Surface Casing

REPAIRING WELL   
ALTERING CASING   
ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3/17/86 - Spud at 7:30 P.M. 3/16/86.

3/18/86 - Ran guide shoe, 40' shoe joint, insert float, 3 centralizers, 11 joints 13-3/8" 61# J-55 ST&C (444.77'). Set at 437.77'. Howco cemented with 450 sacks Class "C" with 2% CaCl and 1/4# flocele. PD to 397.77' at 8:35 A.M. Circulated 146 sacks.

RECEIVED FOR RECORD

*SLW*  
MAR 24 1986

CARISBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Exploration Secretary

DATE 03/19/86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side