Submit 3 Copies to Appropriate

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department Revised 1-1-89 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-30717 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATEX FEE DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 6. State Oil & Gas Lease No. 857948 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" VACUUM GRAYBURG SAN ANDRES UNIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS WELL WELL X OTHER 2. Name of Operator 8. Well No. TEXACO PRODUCING INC. 157 3. Address of Operator 9. Pool name or Wildcat P. O. Box 3109 Midland, Texas 79702 VACUUM GRAYBURG SAN ANDRES Well Location Unit Letter C: 710 Feet From The NORTH 2530 Feet From The WEST Line and Line Township 18-SOUTH Range 34-EAST Section **NMPM** LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) /// GR-3993', KB-4006' Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB X OTHER: OTHER:_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. DRILL 12 1/4 HOLE TO 2800'. TD @ 10:00pm 7-6-90. RAN 62 JTS OF 9 5/8, 36#, J-55, ST&C CSG. SET @ 2800'. 2. HALLIBURTON CEMENTED 1st STAGE - 350 SX 50/50 POZ CLASS H w/ 2% GEL & 5% SALT @ 14.25ppg. F/B 500 SX CLASS H w/ 2% Caci2 @ 15.6ppg. CIRC 200 SX. DID NOT BUMP PLUG. DV TOOL @ 1563'. 2nd STAGE - 720 SX CLASS H w/ 1% Caci2 @ 16.4ppg. CIRC 100 SX. JOB COMPLETE @ 6:00pm 7-7-90. 3. INSTALL WELLHEAD & TEST TO 1000#. NU BOP & TEST TO 3000#. 4. TEST CSG. TO 1500# FOR 30 MIN. FROM 3:00 TO 3:30pm 7-8-90. 5. WOC TIME 21 HRS. FROM 6:00pm 7-7-90 TO 3:00pm 7-8-90. 6. DRILLING 8 3/4 HOLE. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE DRILLING SUPERINTENDENT DATE 07-11-90 SIGNATURE _ TELEPHONE NO. 915-6884620 TYPE OR PRINT NAME C. P. BASHAM GRIGINAL COMED BY JERRY SEXTON (This space for State Use)

. TITLE .

CONDITIONS OF AFFROVAL, IF ANY:

APPROVED BY -

DETERMINE SHITMAN SOR