

OF COPIES RECEIVED	
DISTRIBUTION	
A FE	
S.S.	
D OFFICE	
RATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. State
7. Unit Agreement Name West Vacuum Unit
8. Farm or Lease Name West Vacuum Unit
9. Well No. 27
10. Field and Pool, or Wildcat Vacuum
12. County Lea

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <u>Injection Well</u>
Name of Operator TEXACO Inc.		
Address of Operator P. O. Box 728, Hobbs, New Mexico		
Location of Well UNIT LETTER <u>K</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Convert to Water Injection Well</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

The following work has been completed on subject well to convert to water injection well:

1. Pull the rods and tubing.
2. Clean well out to the total depth of 4646'.
3. Run tubing with Model "A" Packer, and set Packer at 4073'.
4. Connect injection line, effective date 7:00 A.M. October 13, 1967.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. G. Blevins, Jr. TITLE Asst. Dist. Supt. DATE October 13, 1967
APPROVED BY John W. Remy TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: