

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <u>A-1320</u>	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <u>Exxon Corporation</u>		8. Farm or Lease Name <u>NEW MEXICO STATE</u>
3. Address of Operator <u>P.O. Box 1600, Midland, Texas 79702</u>		9. Well No. <u>8</u>
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>28</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>VARUUM (G.R.S.A.)</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3949 GR</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>CSG LEAK SURVEY</u> <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out cellar to surface casing.
- Install bleeder line from 10 3/4" surface casing to above ground level with control valve at surface.
- Install bleeder line from 15/8" intermediate casing to above ground level with control valve at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A L Clemmer</u>	TITLE <u>Unit Head</u>	DATE <u>2-3-77</u>
Orig. Signed by <u>Les Clemmer</u> Oil & Gas Dept.		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 1977

CLC - 1001 F. 101.
FEBES, H. M.