

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SUN OIL COMPANY - DX Division	8. Farm or Lease Name M. Caylor
3. Address of Operator P. O. Box 1416, Roswell, New Mexico 88201	9. Well No. 6
4. Location of Well UNIT LETTER <u>E</u> <u>902</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>6</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Lovington Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3826' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER _____ <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in pulling unit & csg. jacks.
- Set 35 sx plug from 5882'-6200'. Loaded hole.
- Shot off 5½" csg. at 3795'. Pulled 115 jts.
- Ran tbg. to 3825'. Spotted 25 sx from 3825-3615'.
- Spotted 25 sx plug from 3200-3090'. (Bottom of intermediate csg.)
- Cut off csg. head, set 10 sx plug in surface.
- Installed dry hole marker, cleared location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jo Bob Hille TITLE Acting District Engineer DATE 3/9/70

APPROVED BY John W. Runyan TITLE Geologist DATE MAY 5 1971

CONDITIONS OF APPROVAL, IF ANY: