

CAYALLA: 21-3
 (LINAM FROM NO. 1)
 SECTION 21-185-32E
 660' FAL 1930' FSL
 LRA COUNTY NEWARK

SURFACE CSL: 13 3/8" 48# @ 753'
 13 1/4" 48# @ 753' INT. 8 5/8" 24# 32# @ 3465'
 CPT CIRC PRODUCTION CSL: 5 1/2" 17# @ 10,787'
 GL: 3760 KB: 3774 TD: 11,747

8 5/8" 24-32# @ 3465'
 CPT CIRC

5 1/2" 17# IO 4.892" DRIFT 4.767'

COLLAPSE 4910# BUIST 5320'

STAIN
 1,400 - 1,500
 Top line -
 8500'
 End of
 production

~ CPT TOP 8300'

(BUNK SPRINGS)
 8708-8716
 502 w/100 SX

(WOLF CAMP)
 10502-516
 10625-712 } 502 w/300 SX
 5 1/2" 17# @ 10,787'

SPOT 50 SX @ 10,287'

7 7/8" Hole To 11,747'

SPOT 25 SX @ 11,727'

SPOT 25 SX @ 12,244'

TD 12813'

Completion Record

WOLF CAMP
 11-15-65: P/10,625-712 A/5200
 WOLF CAMP
 12/10,502-516 A/2800
 BUNKS SPRINGS
 12/8708-8716 A/5000
 QUALITY LOGGING WELL
 1-27-67: 502 BUNKS SPRINGS 8708-8716
 w/100 SX
 2-24-82: 502 WOLF CAMP 10,502-712
 w/300 SX.
 DILLO 10,787-12812 (MURROW TEST)
 UNSUCCESSFUL, DILLO WELL TO SURF.
 10-19-85: REENTRANCE TO 9900'
 2-22-89: RAN CSL INSP LOG 9900-8000
 CBL 9900-8000

TCR 10/25/90