

EVGSAU Tract 3236, Well #006  
W. O. #602502  
CONVERSION TO INJECTION  
Vacuum Grayburg San Andres Field  
Lea County, New Mexico  
Page 2

2. Prior to injecting water, run PPGCo. pressure recorder to 4600', taking gradient stops at 3500', 4000' and 4500'. Leave on bottom 15 minutes.
3. Wellhead pressure not to exceed 860 psi. Do not inject water under pressure without automated pressure control or "Pop-Off" device. Notify NMOCD's Hobbs District Office before injection is commenced.

MHB:lbb  
Attachments

cc: E. E. Clark  
D. T. Thorp (2)  
G. R. Smith  
S. H. Oden  
W. J. Mueller  
L. J. Scott  
E. C. Wiszneauckas (2)  
M. H. Brownlee  
T. H. McLemore  
W. J. Durham  
N. B. Maddux  
(r) W. D. Steinbeck  
Central Files

RECEIVED  
NOV 17 1982  
C.C.O.  
HOBBS OFFICE