

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-04355
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E1083
7. Lease Name or Unit Agreement Name State A
8. Well No. 1
9. Pool name or Wildcat Eumont Yates 7 Rvrs. Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator James L. Evans	
3. Address of Operator P.O. Box 1029 Eunice, NM 88231	
4. Well Location Unit Letter <u>L</u> : <u>330</u> Feet From The <u>West</u> Line and <u>1650</u> Feet From The <u>South</u> Line Section <u>27</u> Township <u>20S</u> Range <u>36E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/17/93

Pumped 35 sacks of Class C cement at 3,700'. Pulled up, waited on cement, tagged cement at 3,350', circulated 10lbs. of salt gel mud. Pulled tubing to 1,000', spot 25 sacks of cement, pulled tubing out, perf 5½ casing at 261 foot. Pumped 50 sacks down 5½ casing to 261' up 8 5/8 to surface. Cut off well head, set marker with 10 sacks of cement. Will move tank battery and clean location in the near future.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James L. Evans TITLE Operator DATE 12/1/93  
(505)  
TYPE OR PRINT NAME James L. Evans TELEPHONE NO. 394-3748

(This space for State Use)

ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP. II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: