Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240 WELL API NO. 2040 Pacheco St. 30-025-06974 Santa Fe. NM 87505 sIndicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE STATE DISTRICT III 6State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" J. N. CARSON (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL X OTHER «Well No. 2Name of Operator TITAN RESOURCES I, INC. 1 3Address of Operator Pool name or Wildcat 500 W. TEXAS, STE 500, MIDLAND, TEXAS 79701 **PADDOCK 49210** ₄Well Location 2080 **NORTH** 660 **EAST** Unit Letter Feet From The Line and Feet From The Line 33 **21S** 37E Section Township Range _EA County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3449' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: RE-ENTER P&A WELL AND COMPLETE IN PADDOCK 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 6/10/97 Dig out csg. stub. Install new wellheead. MIRU pulling unit and reverse rig.
6/11/97 Tagged surface cmt plug @ 72'; drilled to 284'.
6/12/97 Drilled to 335'; base of surface plug. RIH to 580' & tagged 2nd cmt plug. tested csg to 500 psi; ok. Drilled cmt to 1026'. RIH & tagged cmt at 3471'; crilled to 3700'.

Drilled cmt to 3770' and fell free. Tested csg. to 500 psi, ok; RIH & tagged cmt at 4943'. Drilled to 5188'. 6/13/97 6/17/97 Drilled & cleaned out to 5500'. Rig broke down. 6/18/97 RIH w/ string mill to 5500'.
Ran GR-CNL-CCL from 5500' to 3000'. 6/20/97 6-22-97 6/24/97 Perf L. Paddock w/ 2 spf as follows: 5104-5114'; 5122-5142'; 5150-5160'; 5172-51852'; 5206'-5216' (120 holes); RIH w/ tbg & pkr and acidized perfs 5104-5182' w/ 4000 gal 15% NEFE HCL; RU swab & started swabbing back load. 6/26/97 Swabbing.
6/27/97 POOH w/ tbg & pkr; Perf'd U. Padock 5050-5080' w/ 1 spf (30 holels). RIH w/ RBP & pkr. Set BP @ 5092'. Set pkr @ 4963'. Acidized w/ 3000 gal 15% NEFE HCL. RU swab & swabbed back load.
7/1/97 Swabbed well, POOH & LD workstring.
7/2/97 RIH w/ 2 3/8" prod. tbg; set @ 5273'; RU swab and swabbed well.
7/3/97 Swabbed well. RIH w/ pump and rods. 7/4/97 Finished running pump & rods & started well pumping. 7/5/97 Pumping and testing. I hereby certify that the and complete to the best of my knowledge and belief. TITLE PROD. OPR. MNGR. SIGNATURE DATE 07-17-97 TYPE OR PRINT NAME BRUCE WOODARD TELE PHONE NO. 915-498-8661

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY CHRIS WILLIAMS

DISTRICT I SUPERVISOR

TITLE

1 9 1997

DATE

CONDITIONS OF APPROVAL, IF ANY: