

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company B. A. Ray		1062 JUN 25 PM 3:15 P. O. Box 1385, Midland, Texas					
Lease Blankenship	Well No. 2	Unit Letter L	Section 12	Township 20 South	Range 38 East		
Date Work Performed June 21-22 -67	Pool House Drinkard Pool			County Lea County			
THIS IS A REPORT OF: (Check appropriate block)							
<input type="checkbox"/> Beginning Drilling Operations	<input type="checkbox"/> Casing Test and Cement Job		<input type="checkbox"/> Other (Explain):				
<input type="checkbox"/> Plugging	<input checked="" type="checkbox"/> Remedial Work		Opened lower zone in Drinkard. Bottom of former perforations 7009'				
Detailed account of work done, nature and quantity of materials used, and results obtained.							
Bottom of former perforations was 7009'. Perforated 7021-25 and 7026-28. Opened 6' of 10' zone in the Drinkard							
Guiberson packer set at 7017'. Acidized with 250 gallons mud acid and 3000 gallons of regular acid.							
The old perforations are above packer or behind tubing; so production is from the new zone.							
Witnessed by T. J. Brown		Position Executor		Company R. DeChicchi's Estate			
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY							
ORIGINAL WELL DATA							
D F Elev. 3569	T D 7125		P B T D		Producing Interval 7021-28	Completion Date 6-23-67	
Tubing Diameter 2-3/8 EUE		Tubing Depth 7062		Oil String Diameter 5-1/2"		Oil String Depth 7125	
Perforated Interval(s) Formerly 6968-82, 6991-95; 7003-09'. Now producing from 7021-25 and 7026-28'							
Open Hole Interval None				Producing Formation(s) Drinkard			
RESULTS OF WORKOVER							
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover	2-18-62	28.64	175.7	2.78	6136/1		
After Workover	6-23 to 6-24	196.8	37.2	4.2	1890/1		
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.			
Approved by Lester A. Clement				Name Bernard A. Ray			
Title				Position Owner - Operator			
Date				Company B. A. Ray			