

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 480, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL & 660' FWL
AT TOP PROD. INTERVAL: ☒
AT TOTAL DEPTH: ☒

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Repair casing leak

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rel. pkr. CO to top of liner (8960'). Set RBP @ 9000'.
Set pkr. above RBP and pressure test RBP to 2000 psi w/ TFW. When casing leak interval is found, set RBP 50' below bottom of interval and spot 20' sand on top of RBP. Set pkr. 50' above casing leak interval. Squeeze interval w/100sx Class 'c' cement w/2% CaCl. WOC 18 hrs. POOH w/pkr. DO cement. Pressure test squeeze, repeat squeeze procedure as necessary. POOH w/ RBP. Set pkr @ 8900'. Acidize perts w/500 gal 15% HCL-NE-FE. Return to inject.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. A. Gillham TITLE Administrative Supervisor DATE 3/7/83

APPROVED

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

MAR 11 1983

FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

MAR 14 1983

O.C.D.
HOBBS OFFICE