

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

Min Roswell District  
Modified Form No. 30-025-08110  
NM60-3160-4  
LEASE DESIGNATION AND SERIAL NO.  
NM-77058

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> <i>Re-entry</i>		3a. Area Code & Phone No. 505-622-1127	
2. NAME OF OPERATOR Strata Production Company		8. FARM OR LEASE NAME Cercion Federal	
3. ADDRESS OF OPERATOR P. O. Box 1030, Roswell, New Mexico 88202-1030		9. WELL NO. #7	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1985' FNL & 657' FWL unit E 1980 660		10. FIELD AND POOL, OR WILDCAT East Livingston Ridge Delaware	
11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Section 22-22S-32E		12. COUNTY OR PARISH Lea	
13. STATE NM		14. PERMIT NO.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3678' GR		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) Re-entry <input checked="" type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

see attached wellbore schematic

Strata Production Company plans to re-enter the former John H. Trigg well located 1980' N 660' W  
1985' FNL & 657' FWL, Section 22, Township 22 South, Range 32 East, Lea County, New Mexico, in the following manner:

- 1) Dig out well head and nipple up to 8 5/8" surface casing.
- 2) Drill out plugs at surface, 590', 945', 4410' and 7313'. Circulate hole clean. TOH with drill string. (Will use a cut brine system).
- 3) Log and side-wall core zones of interest.
- 4) Run 5 1/2" 17# casing to TD and cement to surface. Will run a two (2) stage cement program.

APPROVAL SUBJECT TO  
GENERAL REQUIREMENTS AND  
SPECIAL STIPULATIONS  
ATTACHED

\* See attached copy of orig. surveyor plat for corrected footages E & S

18. I hereby certify that the foregoing is true and correct		DATE 1/5/93	
SIGNED <i>Carol J. Garcia</i>	TITLE Production Supervisor		
(This space for Federal or State office use)			
APPROVED BY <i>[Signature]</i>	TITLE <i>[Signature]</i>	DATE 2-8-93	
CONDITIONS OF APPROVAL, IF ANY:			

\*See Instructions on Reverse Side