

|                    |  |
|--------------------|--|
| OF COPIES RECEIVED |  |
| DISTRIBUTION       |  |
| NTA FE             |  |
| LE                 |  |
| .S.G.S.            |  |
| LAND OFFICE        |  |
| OPERATOR           |  |

HOBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 3 3 28 PM '68

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|   |                              |
|---|------------------------------|
| 5a. Indicate Type of Lease                    |                              |
| State <input checked="" type="checkbox"/>     | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br><b>B-8244</b> |                              |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |  |
|---|--|--|
| 1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Jalmat</b>   |  | 7. Unit Agreement Name<br><b>Field Yates Sand Unit</b> |
| 2. Name of Operator<br><b>Gulf Oil Corporation</b>  |  | 8. Farm or Lease Name                                  |
| 3. Address of Operator<br><b>Box 670, Hobbs, New Mexico 88240</b>   |  | 9. Well No.<br><b>109</b>                              |
| 4. Location of Well<br>UNIT LETTER <b>G</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>2310</b> FEET FROM<br>THE <b>East</b> LINE, SECTION <b>11</b> TOWNSHIP <b>22-S</b> RANGE <b>35-E</b> NMPM. |  | 10. Field and Pool, or Wildcat<br><b>Jalmat</b>        |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>3615' GL</b>  |  | 12. County<br><b>Lea</b>                               |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

|  |   |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            |

SUBSEQUENT REPORT OF:

|  |   |
|--|---|
| REMEDIAL WORK <input checked="" type="checkbox"/>    | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> |   |
| OTHER <input type="checkbox"/>                       |   |

**Clean out, reperforate and acidized**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**4015' PB.**

Pulled tubing, rods and pump. Cleaned out from 3977' to 4015'. Perforated 5 1/2" casing with 2, 1/2" JHFF at 3877-84', 3889-96', 3918-20', 3930-32', 3942-50' and 3958-66'. Ran 2-3/8" tubing with perforated nipple at 3968'. Treated perforations with 1000 gallons of 15% NE double inhibited acid. Let set 2 hours. Displaced with 5 BO down tubing and 15 barrels of water. Maximum pump pressure 1500#, minimum 1200# on tubing. Casing pressure 900#. AIR 1.5 bpm, ISIP 900#, after 15 minutes 700#. Pumped 5 BW down casing. Pump pressure 1100#, ISIP 700#. Closed well in overnight. Swabbed and cleaned up. Raised tubing and set at 3975'. Ran rods and pump and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|   |                                      |                          |
|---|--------------------------------------|--------------------------|
| ORIGINAL SIGNED BY<br>SIGNED <u>C. D. BORLAND</u> | TITLE <u>Area Production Manager</u> | DATE <u>June 3, 1968</u> |
| APPROVED BY <u>[Signature]</u>                    | TITLE <u></u>                        | DATE <u></u>             |
| CONDITIONS OF APPROVAL, IF ANY:                   |                                      |                          |