

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 13137

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well Jalmat	7. Unit Agreement Name Field Yates Sand Unit
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 146
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 22-S RANGE 35-E NMPM. Jalmat	10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, GR, etc.) 3593' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3981' TD, 3970' PB.

Could not release packer at 3810'. Cut and recovered 2-1/16" tubing from 3790', leaving 20' 2-1/16" tubing and Larkin packer in hole. Ran CI BP and set at 3778'. Loaded hole with gel water. Spotted 5 sack cement plug on top of BP. Spotted 15 sack cement plug from 2000' to 1850', across salt and 10 sack cement plug from 100' to surface. Installed dry hole Marker and cleaned location. Plugged and abandoned June 18, 1974

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Area Engineer DATE June 18, 1974
APPROVED BY *[Signature]* TITLE Geologist DATE SEP 18 1974
CONDITIONS OF APPROVAL, IF ANY: