Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

## **OIL CONSERVATION DIVISION**

P.O. Box 2088	
DISTRICT   Santa Fe, New Mexico 87504-2088	
P.O. Box 1980, Hobbs, NM 88240	Constant and the second
DISTRICT II P.O. Drawer Dd, Artesia, NM 88210	API NO. (assigned by OCD on New Wells) 30-025-08766
DISTRICT III	Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, Nm 87410	STATE X FEE
	6. State Oil & Gas Lease No.
	B-1732
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	HARRY LEONARD (NCT-D)
1. Type of Well:	
OIL GAS WELL X WELL OTHER	
2. Name of Operator	8. Well No.
CHEVRON U.S.A. INC.	15
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	EUNICE SOUTH SR-QUEEN
4. Well Location Unit Letter P: 660 Feet From The SOUTH Line and	660 Feet From The EAST Line
Section 3 Township 22S Range	36E NMPM LEA County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3567' GL	
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT I	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND ABAN.
PULL OR ALTER CASING CMT JOB	
OTHER: OTHER:	
<ol> <li>Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.</li> </ol>	
WORK PERFORMED 9-30 THRU 10-5-92	
SET CIBP AT 3710', LOAD & TEST ANN TO 300#, OK. CAP BP W/35' (5 SX) CMT. COVERS QUEEN PAY.	
SET BALANCED PLUG F/3470-3120. (35 SX.)COVERS YATES & 7-RIVERS PAYS.	
PERF @ AT 1715' SET PKR @ 1500, ESTAB INJ RATE 1/4 BPM, 800#.	
SPOT 25 SX PLUG F/1800-1600'. POH & SQZ 1/2 BBL CMT INTO PERFS @ 1715'.	
SWI F/30 MIN. PERF 4 HOLES @ 450',, BRK CIRC BETWEEN 5-1/2 & 8-5/8 CSG. PMP 120 SX	
CIRC CMT TO SURF. CUT OFF WELLHEAD & CUT OFF ANCHORS, ND & INSTALL P & A MARKER.	
10# P & A MUD WAS PLACED BETWEEN ALL CMT. PLUGS.	
CHANGE WELL STATUS TO P & A.	
NOTE: OCD REP RAY SMITH OK'D CHANGE OF P&A PROCEDURE	
NOTE: OCD REPRAY SWITH ON D CHANGE OF PAA PROCEDURE	
I hereby certify that the information above is you and complete to the best of my knowledge and belief.	
SIGNITURE TULE TITLE TECHNICAL ASSISTANT	DATE: 10/19/92
TYPE OR PRINT NAME NITA RICE	TELEPHONE NO. (915)687-7436
A second	
APPROVED BY THE F. MITTER OIL & GAS LINE -	DEC 2 8 '92
CONDITIONS OF APPROVAL, IF ANY:	