

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

Oil Conservation Division

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>35-025-08815</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J H Day
8. Well No. 1
9. Pool name or Wildcat SWD Jalmat Seven Rivers
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3591' KB 3601

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☐ SWD

2. Name of Operator
McCasland Services, Inc.

3. Address of Operator
PO Box 99 Eunice, NM 88231

4. Well Location
Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line
Section 6 Township 22-S Range 36-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GL 3591' KB 3601

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Clean out open hole</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PU.
- 2) ND WH, release pkr, Install BOP & POOH w/tbg & pkr.
- 3) PU bit. DC & work string. RIH. Tag fill @ 3778'. Clean out to 3846'. POOH. lay down work string, DC & bit.
- 4) PU 5 1/2" x 2 3/8" AD-1 pkr & RIH w/ 121 jts. of 2 3/8" plastic coated tbg. Circ. pkr fluid & set pkr @ 3699'. NU WH.
- 5) Casing test to 540#, for 27 min. Held.
- 6) Return to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray D. Ramsey TITLE Company Rep. DATE 2/23/94

TYPE OR PRINT NAME Ray D. Ramsey TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 28 1994

CONDITIONS OF APPROVAL, IF ANY:

JCB