

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
030132

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Cities Service Oil Company | 8. Farm or Lease Name Closson |
| 3. Address of Operator % Hobbs Pipe & Supply Co., Box 2010, Hobbs, N.M. 88240 | 9. Well No. #2 |
| 4. Location of Well UNIT LETTER H 1980 FEET FROM THE north LINE AND 660 FEET FROM THE west LINE, SECTION 18 TOWNSHIP 22-S RANGE 36-E N.M.P.M. | 10. Field and Pool, or Wildcat South Eunice |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3582 | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JCB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

1. Propose to spot a 25 sack cement plug at 3805'.
2. Propose to spot a 25 sack cement plug at 3100', stub of 5 1/2" & 8 5/8" shoe.
3. Propose to spot a 10 sack cement plug at surface with marker.
4. Hole will be loaded with mud laden fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Arnold Schneider* TITLE Agent DATE 11-21-69

APPROVED BY *J. G. Smith* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: