

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20932
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name L.R. KERSHAW
8. Well No. 10
9. Pool name or Wildcat MONUMENT TUBB & SKAGGS DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Texaco Exploration and Production Inc.

3. Address of Operator

P. O. Box 730 Hobbs, NM 88240

4. Well Location

Unit Letter F : 2080 Feet From The NORTH Line and 2310 Feet From The WEST Line
County

Section 13 Township 20-S Range 37-E NMPM LEA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3562' (DF)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/15/92 - 12/18/92

1. MIRU. TOH W/ PROD EQUIP FROM WEST STRING. TIH IN EAST STRING, CLEANED OUT TO 5700'.
STARTING DATE 12/15/92.

2. TIH IN WEST STRING, ESTD RATE INTO TUBB & DRINKARD PERFS, PMPD 200 SXS CLASS C CMT DOWN STRING.

3. TIH IN EAST STRING TO 5700', SPTD 8 SXS CMT, TOC @ 5269'. TOH TO 2678', SPTD 345' CMT PLUG,
TOC @ 2333'. TOH TO 1503', SPTD 345' CMT PLUG, TOC @ 1158'. TOH TO 222', SPTD CMT TO SURFACE.

4. TAGGED CMT IN WEST STRING @ 1000', SPTD CMT TO SURFACE IN WEST STRING.

5. CUT OFF WELLHEAD, INSTALLED DRY HOLE MARKER, CLEANED LOCATION. COMPLETION DATE 12/18/92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 1-6-93

TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Charles R. ... TITLE OIL & GAS INSPECTOR DATE JUL 07 1994

CONDITIONS OF APPROVAL, IF ANY: