

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-27250
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3524
7. Lease Name or Unit Agreement Name Berry APN State
8. Well No. 1
9. Pool name or Wildcat Berry Bone Springs, North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3731' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South Fourth Street - Artesia, NM 88210

4. Well Location  
Unit Letter T : 1980 Feet From The South Line and 660 Feet From The West Line  
Section 5 Township 21S Range 34E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Commence re-entry <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-6-95 - Started dirt work. Removed dry hole marker. Started jack hammering out cellar around wellhead. Cellar is full of cement. NOTE: Notified OCD-Hobbs of commencing re-entry.

10-7-9-95 - Worked on cellar, wellhead and location.

10-10-95 - Installed wellhead. Finished dirt work. Set and tested anchors.

10-11-95 - Finished work on cellar. Moved in and rigged up pulling unit. Set tanks and rigged up reverse equipment. Installed tubinghead and BOP.

10-12-95 - Picked up 6-1/8" bit, drill collar and power swivel. TIH and tagged cement plug at 7'. Started drilling on plug. Drilled down to 30'. TOOH with bit. TIH with blade bit to 30' and continued drilling cement plug. Drilled out of cement at 152'. NOTE: Spudded at 8:30 AM 10-11-95.

10-13-95 - TIH and tagged 2nd plug at 1617'. Circulate casing clean and started drilling on 2nd plug. Drilled down to 1711'. TOOH with blade bit. TIH with 6-1/8" mill tooth bit, drill collars and 2-7/8" tubing. Resumed drilling cement at 1711'. Drilled out of cement plug at 1821'. TIH and tagged 3rd plug at 3476'. Drilling on cement plug.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 10-24-95  
 TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNATURE OF RUSTY KLEIN  
DISTRICT III

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

01 21 1995

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-27250
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-3524
7. Lease Name or Unit Agreement Name	Berry APN State
8. Well No.	1
9. Pool name or Wildcat	Berry Bone Springs, North
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3731' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	YATES PETROLEUM CORPORATION
3. Address of Operator	105 South Fourth Street - Artesia, NM 88210
4. Well Location	Unit Letter <u>T</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>5</u> Township <u>21S</u> Range <u>34E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Re-entry <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-14-95 - Continue drilling cement. Drilled out of cement plug at 3729'. Dropped down and tagged plug #4 at 5560'. Circulated casing clean. Started drilling on cement plug #4 at 5560'. Drilled out of cement at 5754'. Dropped down and tagged plug #5 at 8483'. Circulated casing clean. Started drilling on cement plug #5 at 8483'.

10-15-95 - Continue drilling on cement plug. At 8726', started drilling on junk. Drilled cement at steel to 8370'. Circulate casing clean. Tested casing to 1500 psi. Started out of hole with 2-7/8" tubing. Rig broke down. Shut down for rig repairs.

10-16-95 - Shut down for rig repairs.

10-17-95 - TOOH with tubing, drill collars and bit. Middle of bit worn out from drilling on metal. TIH with 6-1/8" shoe, 1 joint of wash pipe, drill collars and 2-7/8" tubing. Tagged up at 8730'. Riggged up power swivel. Drilled cement down to 8733'. Started milling on metal at 8733'.

10-18-95 - Continue milling on packer.

10-19-95 - Milling on packer.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 10-24-95  
 TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-025-27250

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
V-3524

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
  
Berry APN State

1. Type of Well:  
Oil Well  Gas Well  Other

8. Well No.  
1

2. Name of Operator  
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat  
Berry Bone Springs, North

3. Address of Operator  
105 South Fourth Street - Artesia, NM 88210

4. Well Location  
Unit Letter T : 1980 Feet From The South Line and 660 Feet From The West Line  
Section 5 Township 21S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3731' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Re-entry</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-95 - Milling on packer.  
10-21-95 - Milling on packer. Packer turned loose and pushed down hole to 8882'. TOOH with shoe & tubing. TIH with 6" lead block. Tagged packer at 8882' with 2000#. Moved packer down hole to 8959'. TOOH with lead block.  
10-22-95 - TIH with new shoe. Tagged packer at 8959'. Pushed packer to 11320'. TOOH with shoe, jars and drill collars. TIH with bit and scraper to 10800'. Circulated hole with 2% KCL water. TOOH. Shut down.  
10-23-95 - Prep to resume operations.  
10-24-95 - TIH with packer and 2-7/8" tubing. Set packer at 8873'. Tested casing below 8873' to 2800 psi for 10 minutes. Pulled up and set packer at 8783'. Tested casing above 8783' to 2700 psi for 10 minutes. TOOH with tubing and packer. Rigged up wireline. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools. Shut down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 10-24-95  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_