

copy

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name Lou Wortham
3. Address of Operator P. O. Box 806, Eunice, New Mexico	9. Well No. 4
4. Location of Well UNIT LETTER F, 1750 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 22S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Penrose-Skelly
15. Elevation (Show whether DF, RT, GR, etc.) 3366' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU and pull rods & tubing.
2. Run sand pump & clean out to TD.
3. Fracture treat w/90,000 gals. 9# gelled brine, 54,000# 20/40 & 54,000# 10/20 sand in 4 stages. Using 3 block stages rock salt.
4. Run tubing, rods, & pump.
5. RDPU & put well pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. Anderson Date 5-9-75 TITLE Area Supervisor

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 12 1975

OIL CONSERVATION COMM.
HOBBS, N. M.