

to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1880, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer Dd, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-10359 <input checked="" type="checkbox"/>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
8. Well No. 245
9. Pool name or Wildcat ARROWHEAD/GB
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3410' GL

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
CHEVRON U.S.A. INC.

3. Address of Operator  
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location  
Unit Letter B : 660 Feet From The NORTH Line and 1980 Feet From The EAST Line  
Section 119-19 Township 22S Range 37E NMPM LEA County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
	PLUG AND ABAN. <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 5-7-93 THRU 5-26-93  
POH W/RODS & PMP, ND WH, NU BOP. DEEPEN WELL TO 3813, RUN GR-CCL-SPECTRAL LITHODENSITY-CALIPER LOG. LOCATE CSG LEAK @ 393-1016, SET RBP @ 1500' SPOT 15' SD ON TOP. CIRC HOLE W/FRESH WTR. SPOT 80 SX CL-C CMT F/300-1040, PRES UP TO 450#. WOC. DRL OUT CMT TO 1040', POH W/RBP, ACDZ OH W/20 BBLS 15% NEFE HCL. PMP 1500 GAL ACID. SWB BACK LOAD. PERF 2 JHPF, 3704-3663. ACDZ NEW PERFS W/26 BBLS SWAB. RUN TBG, ND BOPE, NU WH. RETURN TO PRODUCTION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 6/2/93

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY DISTRICT I SUPERVISOR TITLE \_\_\_\_\_ DATE JUN - 7 1993

CONDITIONS OF APPROVAL, IF ANY:

mp

JUN 0 3 1993  
OCD HOBBS OFFICE