

Submit 3 Copies  
to Appropriate  
District Office  
District I  
P.O. Box 1980, Hobbs, NM 88240  
District II  
P.O. Drawer DD, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

WELL API NO.	30 - 025 - 10540
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B3480
7. Lease Name or Unit agreement Name	SKELLY PENROSE B UNIT
8. Well No.	9
9. Pool name or Wildcat	LANGLIE MATTIX 7 RVR Q-GB

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator	OXY USA INC.
3. Address of Operator	P.O. Box 50250 Midland, TX 79710
4. Well Location Unit Letter <u>K</u> : <u>1,980</u> Feet From The <u>SOUTH</u> Line and <u>2,310</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>22 S</u> Range <u>37 E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3,383

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3800' PERFS - 3644' - 3778'

MIRU PU 6/1/93, NDWH, NUBOP, POOH W/ 2' TBG SUB, RIH W/ RBP & SET @ 375', CIRC HOLE, 8-5/8" CSG MOVING. DIG OUT CELLAR, TEST CSG 3'-375' HELD OK. CUT OFF 5-1/2" & 8-5/8" CSG, WELD ON RISERS TO SURF & INSTALL NEW WH ON BOTH. POOH W/ RBP & RIH & TAG @ 3764', CO TO 3800'. POOH W/ PKR & TBG. RIH W/ CIBP & SET @ 3579', CIRC HOLE W/ CORR INHIB, POOH W/ TBG, NDBOP, NUWH, TEST CSG TO 480# - 25MIN, RDPV 6/9/93. WELL IS TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 24 93  
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUL 06 1993

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary Abandonment Expires 7.1.98

RECEIVED

JUN 25 1993

ED HOBBS -  
OFFICE