

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

U.S. DEPARTMENT OF THE INTERIOR

NEW MEXICO

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

5. Lease Designation and Serial No.

LC032104

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number

BLINEBRY, A. H. FEDERAL NCT-1

7

9. API Well No.

30 025 12138

10. Field and Pool, Exploratory Area

South Brunson Drinkard - Abo

11. County or Parish, State

LEA, NEW MEXICO

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No.

205 E. Bender, HOBBS, NM 88240

397-0442

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter G : 1980 Feet From The NORTH Line and 74 Feet From The

EAST Line Section 19 Township 22S Range 38E

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Attering Casing
☐ OTHER: _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*.

Objective: Texaco intends to plug - back the current Granite Wash completion and perforate the South Brunson Drinkard - Abo formation.

1. MIRU. TOH with production equipment. Installed BOP.
2. 2-12-96 TIH with CIBP and sat @ 7327' (Granite Wash perforations @ 7378'-7480'). Test CIBP to 1000#.
3. 2-14-96 Perforated Drinkard - Abo formation with 2 jsfp on interval 7046'-7270'.
4. Acid treated new perforations with 20000g 20% NEFE acid with CO2 + ball sealers.
5. 2-17-96 Perforated Drinkard - Abo with 2 jsfp on interval 6750'-6948'.
6. Acid treated new perforations with 20000g 20% NEFE acid with CO2 + ball sealers.
7. 2-21-96 TIH with production equipment and return to production.
8. OPT TEST 3-6-96 Pumping 24 Hours 80 BOPD, 7 BOWPD, 235 MCFPD.

14. I hereby certify that the foregoing is true and correct

SIGNATURE Paul R. Wilcox TITLE Field Technician

DATE 4/26/95

TYPE OR PRINT NAME Paul R. Wilcox

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

2A Wants Granite Wash dp