

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER O 990 FEET FROM THE South LINE AND 1920 FEET FROM
THE East LINE, SECTION 32 TOWNSHIP 22S RANGE 38E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

T. R. Andrews

9. Well No.

4

10. Field and Pool, or Whidcat

S. Paddock

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER scale treat, perf, acidz. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to treat for sulfate scale, perforate an additional pay (5222-44) w/ 1 JHPF, acidize perfs 5202 -44 w/3000 gallons 15% NEFE HCL. Swab back residue, return in w/ production equipment, turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

L. K. Sexton
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE Technical Assistant

DATE 12-12-88

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE DEC 13 1988

RECEIVED

DEC 12 1988

NOBS OFFICE

NOBS

NOBS OFFICE