

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2068
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-

50. Indicate Type of Lease
State ☐ Fee ☒
51. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OILFIELD PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "I" FORM C-101 FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Gulf Oil Corp.

3. Address of Operator
P. O. Box 670, Hobbs, NM 88240

4. Location of Well
UNIT LETTER F 1780 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 28 TOWNSHIP 22S RANGE 37E N.M.P.M.

5. Elevation (Show whether D.F., K.T., G.R., etc.)
3350' GL

6. County
Lea

7. Unit Agreement Name

8. Term or Lease Term
A. L. Christmas (ARTD)

9. Well No.
1

10. Field and Pool, or Wildcat
Blinbury

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Port up prod. cap. Set CIBP @ 5467' test 500#. Spot 35' Cmt on CIBP. Spot the following plugs:
5175'-5075' (10 cu), 3972'-3872' (10 cu), 3466'-3366' (10 cu),
2546'-2346' (20 cu), 1300'-1100' (20 cu), 60' surf plug (60 cu).
Set dry hole marker. Clear + Clean loc. P+H 5-2-85.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY R. D. Pitre TITLE AREA ENGINEER DATE 5-15-85
R. A. Sullivan TITLE OIL & GAS INSPECTOR DATE SEP 16 1987

CONDITIONS OF APPROVAL, IF ANY: