

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO RE-OPEN OR TO CORK A WELL BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR RE-ENTRY OF (OIL) C-101, FOR GAS C-102, FOR WATER C-103.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.																				
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER 2. Name of Operator Gulf Oil Corporation 3. Address of Operator Box 670, Hobbs, N.M. 88240 4. Location of Well UNIT LETTER <u>F</u> <u>1780</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.		7. Unit Agreement Date 8. Farm or Lease Name A.L. Christmas (NCT-D) 9. Well No. 1 10. Field and Pool, or Wildcat Drinkard																				
15. Elevation (Show whether DF, RT, GR, etc.) 3350' G L		12. County Lea																				
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td colspan="2">NOTICE OF INTENTION TO:</td> <td colspan="2">SUBSEQUENT REPORT OF:</td> </tr> <tr> <td>PERFORM REMEDIAL WORK ☐</td> <td>PLUG AND ABANDON ☐</td> <td>REMEDIAL WORK ☐</td> <td>ALTERING CASING ☐</td> </tr> <tr> <td>TEMPORARILY ABANDON ☐</td> <td>CHANGE PLANS ☐</td> <td>COMMENCE DRILLING OPS. ☐</td> <td>PLUG AND ABANDONMENT ☐</td> </tr> <tr> <td>PULL OR ALTER CASING ☐</td> <td>OTHER ☐</td> <td>CASING TEST AND CEMENT JOBS ☐</td> <td></td> </tr> <tr> <td colspan="2"></td> <td colspan="2">OTHER <u>Abandon Drinkard and complete in Tubb.</u> ☐</td> </tr> </table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐	PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐				OTHER <u>Abandon Drinkard and complete in Tubb.</u> ☐	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																				
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐																			
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐																			
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐																				
		OTHER <u>Abandon Drinkard and complete in Tubb.</u> ☐																				
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.																						

6658 P B

New well produced 140 Bbls. oil from Drinkard Pool then all water--Unsuccessful. Abandon Drinkard and re-complete in Tubb. Pulled producing equipment. Set C I B P at 6390'. Perforated 5 1/2" casing with 2--.75" J H P F at 6263-65, 6233-35, 6188-90 and 6108-10. Tested B P at 6390 with 4000#--OK. Acidized new perms. with 2000 gallons 15% NE Slick Acid and frac. with 39,000 gallons gel 8.6# water containing 1# to 2 1/2# SPG. Flushed with 6300 gallons gel water. Ran 2 3/8" tubing, rods and pump will test pump Tubb zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. F. Berlin TITLE Area Engineer DATE 4-15-77

ORIG. SIGNED BY John Runyan TITLE Geologist DATE

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

10-1-67

US CONVENTION
HONORABLE, H. M.