

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.B.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company - Division of Atlantic Richfield Company	8. Farm or Lease Name Shipley "A" WN
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 6
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Jalmat Yates Tansil Yates 7R Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3499.1' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU 10/28/85. POH w/pump & rods, ND WH. Install BOP. POH w/tbg.
- RIH w/tbg OE, pmpd 18 sx Cl H cmt, WOC. Tag TOC @ 3340' new PBD.
- Swbd to clean up, swbd dry. Trtd w/1000 gals 15% NEFE acid, flushed w/20 bbls 2% KCL wtr.
- Rem BOP, NU WH. RIH w/pump & rods. RIH w/tbg.  
Returned well to production in same zone - plugged off perms 3340-3494'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven D. Smith TITLE Dist Prod Supv. DATE 11/12/85

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE NOV 18 1985

RECEIVED  
NOV 15 1985  
O.C.D.  
HOBBS OFFICE