

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

STATE OF NEW MEXICO
COUNTY OF LEA
WELL NO.

Filed approved,
FEDERAL LAND NO. 42, 11114
PLACED, DESIGNATION AND SERIAL NO.
LC-030139 (A)
B. IF INDIAN, AFOFEE, OR TRIBAL NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Continental Oil Company
3. ADDRESS OF OPERATOR
Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

7. UNIT AGREEMENT NAME
NMFU
8. FARM OR LEASE NAME
Lynn "A"
9. WELL NO.
2
10. FIELD AND FOOT, OR WILDCAT
Jalmat Hates, 7 Rivers
11. SEC., TWP., R., OR BLK. AND SURVEY OR AREA
Sec 27, T-23S, R-36E

990' FNL + 990' FWL of Sec. 27

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3425' DF
12. COUNTY OR PARISH **LEA** 13. STATE **N.M.**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) **Clean out, deepen & acidize** ☒
(Note: Report results of multiple completion on Well Completion or Regeneration Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-5-77 WIH. Tagged at 3330'. Circulated + started drilling.
5-6-77 Drilled to 3430'. Swabbed many runs. WIH w/ 4 1/8" OHBP.
could not get down. POOH w/ tbg. WIH w/ 4 1/8" OHBP. Set BP at
3410'. WIH, spotted cmt from 3410' - 3405'.
5-10-77 Swabbed
5-11-77 "
5-12-77 "
5-13-77 "
5-14-77 WIH w/ 4 1/8" OHBP. Set BP at 3360'. Spot 7' Class "C" cmt. w/ 2 1/2
CaCl₂ to 3353'.
5-15-77 Ran tbg., hooked up wellhead.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Wm. R. [Signature] TITLE **Admin. Serv.**

DATE **5/25/77**

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

