

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Federal IC 030187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. E. Lafferty

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Teague Minebry

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA

Sec. 22, T-23E, R-37E

12. COUNTY OR PARISH

Leon

13. STATE

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 980, Kermit, Texas 79745

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' PBL and 1980' FWL

14. PERMIT NO.

Approved 1-8-68

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3296' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Production String ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cleaned out 8-3/4" hole to 3243'. Spotted 100 sacks cement plug from 3226' up to 3037'. Drilled plug to 3070'. Set whipstock, kicked off same at 3060', drld. to 3141', unable to stay out of old hole. Spotted 150 sack cement plug from 3135' up to 2875'. Drilled plug to 2938'. Set whipstock, kicked off at 2938'. Drilled 7-7/8" midstream hole in an indeterminate direction to 6300'. Maximum deviation 4-1/4°.

Ran 188 joints 4-1/2" 9.5# J-55 casing w/4-1/2" x 5-1/2" cross-over and 1 cut joint 5-1/2" 15.5# J-55 casing on top. Set w/shoe at 6300'.

Cemented 1st stage thru shoe w/175 sacks 16% Gulf higel and 280 sacks Incor neat.

Cemented 2nd stage thru IW tool set at 4302' w/180 sacks 16% Gulf higel and 100 sacks Incor neat. TBHC at 2530'. Job complete 2-8-68.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. F. Swannack

TITLE

Area Manager

DATE 2-9-68

(This space for Federal or State office use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 12 1968

*See Instructions on Reverse Side J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid content not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-695229

667-851