

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL UP TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. <b>B-1732</b>
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <b>West Dollarhide Queen Sand Unit</b>	
Name of Operator <b>Skelly Oil Company</b>		8. Farm or Lease Name <b>West Dollarhide Queen Sand Unit</b>
Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>		9. Well No. <b>55</b>
Location of Well UNIT LETTER <b>E</b> <b>1994</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM THE <b>West</b> LINE, SECTION <b>4</b> TOWNSHIP <b>25S</b> RANGE <b>38E</b> NMPM.		10. Field and Pool, or Wildcat <b>Dollarhide Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3150' GR</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- 1) Rigged up pulling unit 12-6-72. Pulled rods and tubing.
- 2) Set 7" bridge plug at 3555'.
- 3) Circulated hole with 10.2# mud.
- 4) Spotted 15 sack cement plug 3480-3555'.
- 5) Spotted 100 sack cement plug 1086-1530'.
- 6) Spotted 10 sack cement plug in top of 7" casing and cellar.
- 7) Set marker.

All intervals not cemented were filled with 10.2# mud. No casing was pulled. 9-5/8" OD 36# casing set at 380', and 7" OD 20# casing set 3584' were left in the hole.  
 Well plugged and abandoned 12-7-72.

DISTRICT OFFICE  
FILE COPY

*Copy to Crockett 2-28-73*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) D. R. Crow D. R. Crow TITLE Lead Clerk DATE Jan. 26, 1973

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: None

10-26-77  
ok

Melba