

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	
3002531483	
5. Indicate Type of Lease	
STATE <input checked="" type="checkbox"/>	FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	
WEST DOLLARHIDE DRINKARD UNIT	
8. Well No.	
115	
9. Pool Name or Wildcat	
DOLLARHIDE TUBB DRINKARD	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
2. Name of Operator			
TEXACO EXPLORATION & PRODUCTION INC.			
3. Address of Operator			
15 SMITH ROAD, MIDLAND, TX 79705			
4. Well Location			
Unit Letter <u>A</u> : <u>121</u> Feet From The <u>NORTH</u> Line and <u>1309</u> Feet From The <u>EAST</u> Line			
Section <u>5</u> Township <u>25S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
3165'			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER: \_\_\_\_\_

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: \_\_\_\_\_ HORIZONTAL COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-20-02/2-24-02 : RUN CIBP & SET @ 6337'. MOVE PKR TO 6328 TO TEST CIBP. REL PKR. TIH W/SANDLINE DRILL & TAG CIBP @ 6337. KNOCK CIBP LOOSE & DROVE DN TO 6802. TIH W/SCRAPER. SET CIBP @ 6350. TIH W/PKR TO 6328. TEST PERFS 6072-6216.  
 2-26-02/3-08-02: MIRU KEY#117. TIH ON DP & TAG CIBP @ 6350. TIH W/WHIPSTOCK. RAN GYRO SURVEY. FINAL SETTING @ 269.7 AZIMUTH. MILL 6337-6342, 6343,6346. TOP OF WINDOW @ 6337. BTM OF WINDOW @ 6343. DRILL 6367,6398,6501,6520,6635,6678,6690,6741,6748,6899,6912,6962, 6974,7025,7047,7089,7135,7150,7189,7193,7200,7215,7245,7328,7358,7370,7400,7496,7506,7654,7664,7749,7906,7969,7989,8033,8043,8096,8102, 8238,8243,8321,8364. FSH WHIPSTOCK OUT OF HLE. TIH W/RBP & SET @ 6003. RIGGING DOWN 3-08-02.  
 3-20-02: MIRU POOL #645. 3-22-02: LATCH ONTO RBP @ 6003. TIH W/2 7/8" PORTED SUB ASSEMBLY. END OF TBG @ 8309. PKR @ 6273. 3-26-02: ACIDIZE DRINKARD LATERAL W/51,600 GALS 20% NEFE, 18,000 GALS WF 130 GELLED WTR & 8000 GALS SCALE INHIB. 3-27-02: REL PKR. TIH W/SANDLINE DRILL & TAG @ 6348. BAIL 2' FILL OFF CIBP. KNOCK OUT CIBP. RUN SUB PUMP. 3-28-02: KNOCK OUT CIBP @ 6350. PUSH CIBP TO 6800. TIH W/2 7/8" TBG TO 5477. 3-29-02: RAN TOTAL OF 195 JTS 2 7/8" TBG. TOP OF PUMP @ 6363. BTM PUMP @ 6458. RIG DOWN.  
 3-31-02: ON 24 HR OPT. PUMPED 134 BO, 515 BW, & 151 MCF

FINAL REPORT.

BHL: 32, 25S, 38E, 210' FSL, 3059/E, 2221 FWL  
 24

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Regulatory Specialist

DATE 5/1/2002

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 915-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ORIGINAL SIGNED BY  
PAUL F. KAUTZ  
PETROLEUM ENGINEER

DATE

**AUG 01 2002**

DeSoto/Nichols 12-93 ver 1.0