

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN _____
(Other ins: _____
verse side) _____

Form approved.
Budget Bureau No. 42-K1424.

5. LEASE DESIGNATION AND SERIAL NO.

032579(e)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Fedl Lease

8. FARM OR LEASE NAME

Carlson B 25

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Justis Tubb Drk.-Fussel.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 25-25S-37E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Westates Petroleum Company

3. ADDRESS OF OPERATOR

Box 33, Jal, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL and 1000' FEL Sec. 25

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3058' BS

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-5-69 - Perforate Tubbs zone with 1/2" holes one hole per int. 55663'-5664'-5704'-5705'-5706'-57-7'-5711'-5713'-5714'-5731'-5733'-5741'-5742'-.
Set bridge plug 55800'. Set fullbore packer 55573'. Acidize with 6000 gal. 15% acid. Run long string of tubing. Set Baker lock set packer 56441'. Run short string of tubing latch into P.S.A. 56410'. Put well back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED W. F. Stull

TITLE Prod. Supt.

DATE 5-5-69

(This space for Federal or State office use)

APPROVED

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

MAY 6 1969

J. E. GORDON

*See Instructions on Reverse Side ACTING DISTRICT ENGINEER

Instructions

General. This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.