

Charles T. Bates Well 1.

<u>Drill Stem Tests</u>						<u>Tool</u>	<u>Formation Press.</u>		<u>Recovery- feet</u>				<u>was</u>
<u>Type of Formation Tested</u>						<u>Open</u>	<u>Flowing</u>	<u>Shut-In</u>	<u>Oil</u>	<u>Water</u>	<u>Mud</u>	<u>Other</u>	<u>Test</u>
<u>Date</u>	<u>Test</u>	<u>From</u>	<u>To</u>	<u>Top</u>	<u>Bottom</u>	<u>Min.</u>							<u>Satis</u>
8-2-56	OH	9066	9085	1	5/8	60	-	1485			330*		yes
8-4-56	OH	9085	9099	1	5/8	60	0	125			30*		yes
8-6-56	OH	9099	9134	1	5/8	105	655	3620		1312	90*		yes

*Gas cut drilling mud.