

GREGORY RAZ

6-1-84

RIPU GRAY WELL SERVICE POH /RODS LAYING DOWN
INSTALL BOP POH /TBC LAYING DOWN. PICK UP RIH W/99
JTS. 2 3/8" 8RD TBC. POH W/TBC STANDING UP.

6-2 6-3 6-4 84

SHUT DOWN Witnessed by R.G. Dillon BLM

6-5-84

R.U. KUYKENDALL WIRE LINE SERVICE SET CIBP AT 3020
RIH W/BAILER DUMP 35K CMT CLASS C 35' PLUG.
RIH W/TBC TO 2430' LOADED HOLE W/9" BRINE PUMP 155K CLASS
C PLUG. FROM 2430' TO 2295' POH W/TBC. RU KUYKENDALL
PERF. 995' W/4.25 SHOTS. RIH W/PKR. + TBC. SET PKR AT
902'. RU HOWCO PUMP INTO FORMATION 1/2 BPM AT 500'
POH W/TBC + PKR. RIH W/HOWCO CMT. RET. + TBC. SET AT 902'
PMP 255K CLASS C CMT. AT 700' INJ RATE 1BPM. 5MIN.
SHUT DOWN. 500' POH W/TBC LAYING DOWN. TIED ONTO TBC HEAD
BROKE CIRCULATION TO SURFACE. PMP 140 5K CLASS C CMT.
CIRCULATED 20 BBL'S TO PIT. RDPV. CUT WELL HEAD OFF
WELDED DRY HOLE MARKER ON

1283 UNIT

881 WATSON PKR.

3690 HOWCO

1956 KUYKENDALL

837 X-L

250 GANG.

779 A-B-C

300 ELLIS WELDING

95 LOOP WELDING

110 JAL WELDING