

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

Submit 3 Copies  
to Appropriate  
District Office

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2008

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-025-20139

5. Indicate Type of Lease

STATE ☐

FED ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Ida Wimberley

8. Well No.

16

9. Pool Name or Wildcat  
Justis Blinebry

Langlie matt  
+ SR GN-GB

To be Drilled R 9740 11/25

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

other

2. Name of Operator

ARCO OIL and GAS COMPANY

3. Address of Operator

P.O. Box 1610, Midland, Texas 79702

4. Well Location

Unit Letter F : 1650 Feet From The West Line and 2310 Feet from The North Line

Section 25

Township 25S

Range 37E

NMPM Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3067 GR

11. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

(Other) ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

(Other) ☐

12. Describe Proposed or completed Operation (Clearly state all pertinent dates, including estimated date of starting any proposed work) SBH RULE 1103.

1. Set CIBP @4978 w/35' of cmt on top of CIBP (Blinebry side).
2. Set CIBP @2940 w/35' of cmt on top of CIBP (Seven Rivers Queen Side).
3. Chemical cut both strings of tbg @1896 & TOO H w/both strings.
4. Spot 30 sx of Cl 'C' neat cmt f/1896'-1796'.
5. Spot 30 sx of Cl 'C' neat cmt f/903'-803'.
6. Circ cmt to surf from 40' w/10 sx of Cl 'C' neat cmt.
7. Cut off wellhead 3' below ground level & anchors. Weld on dry hole marker. Clean location.

Set cement plug on 7R-GN side @ 5000'

set cement PLUG on BLINEBRY SIDE @ 3006'

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

Chris E. Humes

TITLE

Drilling Engineer

DATE

11-24-92

TYPE OR PRINT NAME

Chris E. Humes

TELEPHONE

(915) 688-5477

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

DEC 01 '92

APPROVED BY

TITLE

DATE

CONDITIONS FOR APPROVAL, IF ANY:

# WELLBORE SCHEMATIC

## Ida Wimberley #16

AHC/ARCO Oil and Gas Company  
2310' FNL & 1650' FWL (F)  
Sec 25, T-25S, R-37E, Lea Co., NM  
KB-3068'

Spudded 03/23/63  
Completed 04/06/63

TOC @ 1946' by TS

Blinbry perms 5053' to 5442'.  
TA'd 02/83

7-7/8" hole.  
2-7/8" csg @ 6497'.

TD @ 5500'.

11" Hole.  
8-5/8" casing @ 853'  
Set w/550 sxs cmt. Circ.

7Rvrs Qn Perfs @ 3015' to 3220'

7-7/8" hole.  
2-7/8" csg @ 5494' w/900 sxs cmt.