

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

U. M. OIL CO. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO

5. LEASE DESIGNATION AND SERIAL

LC-067968

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. Sirgo-Collier, Inc.
ADDRESS OF OPERATOR

4. P. O. Box 3531, Midland, TX 79702
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit I, 2350' FSL 150' FEL, Sec 30, T-24-S, R-38-E

7. UNIT AGREEMENT NAME

WDQSU *West Dollarhide Queen Sand Unit*

8. FARM OR LEASE NAME

9. WELL NO.

30-70

10. FIELD AND POOL, OR WILDCAT

Dollarhide Queen

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec 30, T-24-S, R-38-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL 3170' KB 3181.5'

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-4-87 Perforated Queen zone from 3828-50'. Total of 16 holes.

8-5-87 Set 5-1/2" RTTS at 3797' KB
Acidize well with 1500 gal 15% NEFE
Start frac, communication between perfs, no sand on formation, stop frac.
Packer moved 28', then stuck.

8-6-87 Packer won't jar loose, leave RTTS in hole
Top of packer at 3764' KB by wireline
Tubing 38" above top of packer.
Seating nipple open
Well on pump



18. I hereby certify that the foregoing is true and correct

SIGNED

Amy L. Whitley

TITLE Agent

DATE 8-14-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE
SJS

SEP 8 1987

*See Instructions on Reverse Side

CARISBAD, NEW MEXICO

RECEIVED

SEP 8 1987

OCD
HODES OFFICE