STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT OIL CONSERVATION DIVISION

APPLICATION OF THE NEW MEXICO OIL CONSERVATION DIVISION THROUGH THE SUPERVISOR OF DISTRICT III FOR AN ORDER REQUIRING GEO ENGINEERING INC. TO PROPERLY PLUG FORTY-FIVE WELLS LOCATED IN TOWNSHIP 20 NORTH, RANGE 9 WEST, MCKINLEY COUNTY, NEW MEXICO, AUTHORIZING THE DIVISION TO PLUG SAID WELLS, AND ORDERING A FORFEITURE OF THE PLUGGING BOND.

> CASE NO. 11813 Order No. R-10867

ORDER OF THE DIVISION

BY THE DIVISION:

This cause came on for hearing at 8:15 a.m. on July 10, 1997, at Santa Fe, New Mexico, before the New Mexico Oil Conservation Division (the "Division") before Examiner David R. Catanach.

NOW, on this 2^{nd} day of September, 1997, the Division Director, having considered the record and the recommendations of the Examiner, and being fully advised in the premises,

FINDS THAT:

(1) Due public notice having been given as required by law, the Division has jurisdiction of this cause and the subject matter thereof.

(1) Geo Engineering, Inc. is the last known owner and operator of the forty-five (45) wells located in Township 20 North, Range 9 West, in McKinley County, New Mexico listed on Exhibit A to this order.

(2) In compliance with Division Rules and Regulations, the operator of said well, posted a blanket plugging bond in the amount of \$50,000.00 issued by American Manufacturers Mutual Insurance Company.

(3) The purpose of said bond is to assure the Division that the subject well will be properly plugged and abandoned when not capable of commercial production.

(4) Neither the operator, the surety, nor any other interested party appeared at the hearing. The record contains uncontroverted evidence that the wells are in need of plugging.

(5) The subject wells have not produced hydrocarbon substance or have otherwise been inactive for more than one year, and no permits for temporary abandonment has been requested by the operator or approved by the Division.

(6) By virtue of the failure to use the subject wells for a beneficial purpose or to have approved current temporary abandonment permits, the wells are presumed to have been abandoned.

(7) The current condition of the subject wells are such that waste may occur, correlative rights may be violated or fresh waters may be contaminated if action is not taken to properly plug and abandon the wells.

(8) In order to prevent waste, to protect correlative rights, and to protect fresh waters, the wells should be plugged and abandoned in accordance with a program approved by the supervisor of the Aztec District Office of the New Mexico Oil Conservation Division.

(9) At this time, the Division seeks an order directing the operator to plug the wells and if the operator fails to do so, make demand upon the surety to pay the Division so much of the bond amount (up to amount of the bond) as is necessary to pay the costs of plugging the wells.

IT IS THEREFORE ORDERED THAT:

(1) The operator is hereby ordered to immediately plug and abandon the wells listed on the attached Exhibit A to this order.

(2) The operator, prior to plugging and abandoning the wells, shall obtain from the supervisor of the Division Aztec District Office an approved program for said plugging and abandoning and shall notify said Aztec Office of the date and time said work is to commence whereupon the Division may, at its option, witness such work.

(3) Should the operator either fail or refuse to carry out the provisions of this order, the Division shall then take such action as is deemed necessary to have the wells properly plugged and abandoned at which time the Division Director shall make demand upon the surety, American Manufacturers Mutual Insurance Company, to pay so much of the bond amount as is necessary to pay the costs of plugging said wells.

(4) Jurisdiction of this cause is retained for the entry of such further orders as the Division may deem necessary.

DONE at Santa Fe, New Mexico, on the day and year hereinabove designated.

STATE OF NEW MEXICO OIL CONSERVATION DIVISION a o William J. **L**eMay Director

S E A L

Exhibit "A"

× •		٠																									_					
MESAVERDE MESAVERDE MESAVERDE	MESAVERDE Mesaverde Mesaverde	MESAVERDE MESAVERDE	MESAVERDE MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERUE Mesaverde	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE Mesaverde	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERUE Versignen	MESAVERUE	MESAVERDE	MESAVERDE	MESAVERDE	MESAVERDE
		. – –						-												• •									• • •			
	Hash Wash Wash	WASH WASH	HEAN	HEAN	HSAN	HENN		HEAN	H2AM	HORM	HEAN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MINITAIN	MULTALIN MOUNTALIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTALN	NTATINON	NTATINUON	MOUNTAIN	MOUNTAIN	MOUNTAIN	MOUNTAIN
POOL CHACO CHACO CHACO CHACO	CHACO CHACO CHACO	CHACO						CHACO	CHACO	CHACO	CHACO						-													RED M	RED M	RED M
TA TA TA		00	00					Ŭ			,0							9 4 69 (<u>14</u>	L, 11		**		14	16 9 1		4 8	4 (1	• 14	. 12,	щ	12,
		55			44	6 f	1 2 2	1							4 4 7					5 5							~	. 10	1			
I NUMBER -031-20433 -031-2060	-031-20062 -031-20061 - 031-20453	-031-20445	031-20484 031-20901	-031-20644	-2047	-2062(-2062	-2076	-2062	-2048	-2064	-0539	-20398	ZBOZ-	02	9	-2056		-60028	0541	-031-05377	031-0538	031-2055	620 023	2039	5250	20570	-031-05646		2098	-031-05360	05356
	-031-	-031-	0-031- 0-031-	0-031-	-031-	30-031-20620	-031-	-031-	-120-	0-031-20483	0-031-2064		160-	-120-	30-031-60	-031-	-031-		-120-02	-031-	-031-	1	1	1	1001	-725-				0-031-	-031-	-031-
HAN		100	0 0 0 0	000							ŝ	(C)	in i	-					•		n	о е	Ó	m (ŋ	0) (1))	e	m	
FTAGE 1 965/E 360/E 660/E	50/M	1650/W	M M 20	660/E	970/5	1650/E	67/13	1965/2		2310/E	35/E	10/2	50/8	10/E	1920/E	00/E	2/00	13/61		108 100/11	1265/E	1130/E	1610/E	2325/E	3/0012	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	10/11	50/E	1920/E	40/E	13/W	55/W
NS 11 36 36	124	96	0 M 0 M	99	16	2 C	12	5;		500	26	6 (ri (5	23				13					10	9 V 4 F	1 -	24	19	27	21	25
FTAGE 1 165/8 360/8 500/8	300/8 330/8	8/066 8/066	330/N 660/N	N/099	N/0/6	N/066	47/N	620/N	000/N	N/066	N/066	110/5	265/3 275/5	2/2	320/5	490/S	580/S	65/3	450/4	0/0 0/0	225/N	5/N	05/N	N/STI	N/000	N/08	420/N	600/N	15/N	52/N	34/N	344/N
				30 160			-						03W 20			-			17 MADU											4	00 -	09W 13
-			20N 0 20N 0		_			-	D NOZ				D NOZ			-	_		D C NOC		-						_		_		_	20N 0
5111 51 51 51 51 51 51 51 51 51 51 51 51																																-
50.00	4 64 Z	22	«	< <			-	m 1	n 4	1 A	а	0	00	0	0	0	0		4 A	-			-	-	9 9			-		υ		F 4
WELL NO 113 110 19	101		_				-		~		•••		~ ~	_		-											_					-
MELI 113 110 RR 119	127	22	96	~~ «) , (א מ	1	26	40	1 (1)	22	თბ	0 a	กัก	4	23	47	ກ້	10	19	~	ω ·	42	22	, c	9 9 m	43	33.	ŝ	13	21	20
		ËË													E		Ë										DH	U H	H OH			
PACIFIC PACIFIC PACIFIC	PACIFIC	PACIFIC								•		PACIFIC	DACTETC	PACIFIC	PACIFIC	PACIFIC	PACIFIC	PACIFIC	PACTETC	PACIFIC	PACIFIC	PACIFIC	PACIFIC	DIALDUA	DI IIIIII	PACIFIC	PACIFIC	PACIFIC	PACIFIC	PACIFIC	PACIFIC	PACIFIC
2000			M M	14 M) 64 1	1. Fd		M E	4 H) [e]	 و هو																			ei S		A FE
SANTA SANTA SANTA SANTA	SANTA	SANTA	STATE	STATE	STATE	STATE	STATE	STATE	STATE	STATE	STATE	VENES	VINES	SANTA	SANTA	SANTA	SANTA	ATNA2	SANTA	SANTCA	SAVITA	SANTA	VINUS		S ANTA	SANTA	SANTA	SANTA	SANTA	SANTA	SANTA	SANTA
					INC		INC	UNI UNI		INC	INC				INC	INC	UNI		INC	INC	UNI					INC	INC	INC	INC	UNI	UNI	INC
RING	RING	RING	RING	RING	RING	S NG	RING	RING	RING	RING	RING	RING	SUNTA SUNTA	BLING	RING	RING	RING	SN17	BNING	RING	RING	DNTN	9 X T X			RING	RING	RING	RING	RING	RING	RING
ator Engineering Engineering Engineering Engineering	ENGINEERING	Engineering	Engineering	engineering	ENGINEERING	ENGINEERING ENGINEERING	ENGINEERING	SNITAZALING SNITAZALING	ENGINEERING	ENGINEERING	ENGINEERING	engtneering Engtneering	ENGTNEERTNG	ENGINEERING	ENGINEERING	ENGINEERING	ENGTNEERING ENGTNEERING	ontraantona Snitraantona	ENGINEERING	ENGINEERING	ENGINEERING	ENGINEERING ENGINEERING	ONTRACTOR	ontragantong	SNITNEED TWC	ENGINEERING	ENGINEERING	ENGINEERING	ENGINEERING	ENGINEERING	ENGINEERING	ENGINEERING
2000										-										-			• •		• •		-	-				-
					88		010			Oab									029	OBD							030	000	010			020
																								_	_							

•