

Meter #: 17611-00
Name: NO VAC ABO UN TR10

Sample

Date: 01/13/2021
Type: Spot
Pressure: 27.0 H2O: lbs/mm
Temperature: 62.0 H2S: ppm

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide, CO2	0.3418		0.6160
Nitrogen, N2	2.9697		3.4066
Methane, C1	64.4721		42.3538
Ethane, C2	16.3870	4.4026	20.1776
Propane, C3	10.3805	2.8730	18.7441
Isobutane, iC4	1.1049	0.3632	2.6297
n-Butane, nC4	2.5505	0.8078	6.0703
Isopentane, iC5	0.5153	0.1893	1.5223
n-Pentane, nC5	0.4626	0.1685	1.3667
Hexanes Plus, C6+	0.8157	0.3576	3.1129
Water, H2O			
Hydrogen Sulfide, H2S			
Oxygen, O2			
Carbon Monoxide, CO			
Hydrogen, H2			
Helium, He			
Argon, Ar			
Totals	100.0001	9.1620	100.0000

Property	Total Sample
Pressure Base	14.730
Temperature Base	60.00
Relative Density	0.8469
HV, Dry @ Base P,T	1412.51
HV, Sat @ Base P, T	1387.79
HV, Sat @ Sample P, T	
Fws Factor	
Cricondentherm	
HCDP @ Sample Pressure	
Free Water GPM	
Stock Tank Condensate Brls/mm	
26 # RVP Gasoline	1.083
Testcar Permian	0.747
Testcar Panhandle	0.901
Testcar Midcon	0.770

NVAU 120 BTY

MTD Avg Gas – Prod Gas = Vented Gas/ Day

11/20/2021 – 11/20/2021 = 81

Pressure Base Conversion

14.73/15.025 = .98036605

80 * .98036605 = 78 mcf Vented

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 65188

QUESTIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 65188
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites	
Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Well	Not answered.
Incident Facility	[fAPP2123056431] NORTH VACUUM ABO 120 BATTER

Determination of Reporting Requirements	
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.	
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	FLARE STACK

Representative Compositional Analysis of Vented or Flared Natural Gas	
Please provide the mole percent for the percentage questions in this group.	
Methane (CH4) percentage	64
Nitrogen (N2) percentage, if greater than one percent	3
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)	
Date venting and/or flaring was discovered or commenced	11/20/2021
Time venting and/or flaring was discovered or commenced	12:00 AM
Time venting and/or flaring was terminated	11:59 PM
Cumulative hours during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Cause: Midstream Emergency Maintenance Other (Specify) Natural Gas Vented Released: 78 Mcf Recovered: 0 Mcf Lost: 78 Mcf

Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	FLARE STACK
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	No
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	DCP MIDSTREAM EQUIPMENT FAILURE. LINE LEAK AT DOBBS BOOSTER STATION
Steps taken to limit the duration and magnitude of venting and/or flaring	DURATION AND MAGNITUDE OUT OF OUR CONTROL DUE TO MIDSTREAM EQUIPMENT FAILURE. CROSS TIMBERS ENERGY MINIMIZES EMISSIONS WHERE POSSIBLE.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	CAUSE AND REOCCURANCE OUT OF OUR CONTROL DUE TO MIDSTREAM EQUIPMENT FAILURE. CROSS TIMBERS ENERGY WILL SI GAS WELLS IF FEASIBLE TO REDUCE AMOUNTS VENTED/FLARE UNTIL MIDSTREAM COMPANY COMPLETES REPAIRS

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 65188

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 65188
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
savarello	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/6/2021