

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 317989

QUESTIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 317989
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2403357992
Incident Name	NAPP2403357992 STATE 2207 36D 193H @ 30-043-21308
Incident Type	Release Other
Incident Status	Initial C-141 Approved
Incident Well	[30-043-21308] STATE 2207 36D #193H

Location of Release Source

Site Name	STATE 2207 36D 193H
Date Release Discovered	01/31/2024
Surface Owner	State

Liner Inspection Event Information*Please answer all the questions in this group.*

What is the liner inspection surface area in square feet	6,751
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	02/29/2024
Time liner inspection will commence	10:15 AM
Please provide any information necessary for observers to liner inspection	CHAD SNELL 505-44-0586 AND JIM MARS 505-947-2460 WILL BE ONSITE
Please provide any information necessary for navigation to liner inspection site	From the intersection of US Hwy 550 & US Hwy 64 in Bloomfield, NM, travel Southerly on US Hwy 550 for 53.6 miles to Mile Marker 97.7; Go Right (Southerly) on Indian Service Route #474 for 3.6 miles to fork in roadway; Go Right (Southerly) which is straight continuing on Indian Service Route #474 for 1.0 miles to fork in roadway. Go Left (Southerly) continuing on Indian Service Route #474 for 0.1 miles to fork in roadway; Go Right (Southerly) which is straight exiting Indian Service Route #474 entering Indian Service Route #46 for 3.4 miles to 4-way intersection in roadway; Go Right (Westerly) exiting Indian Service Route #46 for 2.9 miles to access on right-hand side of existing roadway to State 2207-36D #193H location. Actual coordinates can be found on the initial C-141 for navigation.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 317989

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 317989
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
hhuntington	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	2/27/2024